

C . Proposed Underpass Improvements

Overpass:	Lighting:	Pedestrian Railings:	Sidewalk Condition:	Walls/Abutments:	Plantings:	Bridge Facings:
 <p>San Pablo Avenue North of Barrett</p>	<p>24/7 Illumination should be installed above sidewalks</p>	<p>Install pedestrian railings on both sides of the street</p>	<p>Sidewalks should be widened by narrowing width of San Pablo Ave.</p>	<p>East side has mural by J. Wurlie. West side must have similar mural</p>	<p>Abutments are currently planted.</p>	<p>"Richmond" is painted on each facing (should be maintained)</p>
 <p>Barrett Avenue</p>	<p>24/7 Illumination should be installed above sidewalks on both sides of the street</p>	<p>Install pedestrian railings on both sides of the street</p>	<p>Sidewalks should be widened by installing pavers in existing area intended for planting</p>	<p>Overpass rests on dirt embankments that should be covered with decorative pavers.</p>	<p>Areas exposed to sunlight have been planted with 'rock roses' and other plants. Palms or Redwoods should be added to create 'gateways'</p>	<p>Street name should be painted on facings</p>
 <p>Macdonald Avenue</p>	<p>Lighting was recently installed on south wall. Must also be installed on the north wall</p>	<p>Bollards were installed on the south wall. Bollards or railings should be installed along the sidewalk on the south side of the street.</p>	<p>Sidewalk on north side of the street must be widened. Street embedded lights should be installed in the cross walk where northbound traffic exits I-80.</p>	<p>The south wall has an intact mural by John Wurlie. A similar mural should be painted on the north wall</p>	<p>A Coastal Redwood grove should be planted in the center of the exit circle. Redwoods should be planted on the east side of the overpass.</p>	<p>Street name should be painted on Facings. A second option would be to encourage vines to grow across the face of the overpass.</p>

Overpass:	Lighting:	Pedestrian Railings:	Sidewalk Condition:	Walls/Abutments:	Plantings:	Bridge Facings:
 <p data-bbox="380 548 543 570">Cutting Boulevard</p>	<p data-bbox="779 415 905 472">24/7 Illumination needed above sidewalks</p>	<p data-bbox="963 386 1125 500">Install pedestrian railings on both sides of the street. Add safety devices because of commute lane exit</p>	<p data-bbox="1148 386 1310 500">Sidewalks should be widened. Additional pedestrian safety devices should be installed because of commute lane exit.</p>	<p data-bbox="1333 402 1507 480">The overpass rests on dirt embankments that should be covered with decorative pavers</p>	<p data-bbox="1541 423 1667 461">Some planting is already in place</p>	<p data-bbox="1726 415 1892 472">Street name or district should be painted on the bridge facings</p>
 <p data-bbox="394 857 529 878">Potrero Avenue</p>	<p data-bbox="779 716 919 773">24/7 Illumination should be installed above sidewalks</p>	<p data-bbox="963 695 1125 789">railings should be installed on each sidewalk to separate pedestrian and motor vehicles</p>	<p data-bbox="1148 716 1310 773">Sidewalks should be widened using decorative pavers</p>	<p data-bbox="1333 704 1507 782">The overpass rests on dirt embankments that should be covered with decorative pavers</p>	<p data-bbox="1541 695 1696 789">Some planting is already in place. Redwoods or Palms should be planted to create gateway</p>	<p data-bbox="1726 716 1892 773">Street name or district should be painted on the bridge facings</p>
 <p data-bbox="380 1138 543 1159">Carlson Boulevard</p>	<p data-bbox="779 1013 919 1070">24/7 Illumination should be installed above sidewalks</p>	<p data-bbox="963 1013 1125 1070">Install pedestrian railings on both sides of the street</p>	<p data-bbox="1148 1002 1310 1079">Widen sidewalks by narrowing street by 18" to 24" on each side.</p>	<p data-bbox="1333 1013 1524 1070">Install <u>ceramic tile</u> murals on each concrete abutment</p>	<p data-bbox="1541 992 1667 1029">Some planting is already in place.</p>	<p data-bbox="1726 992 1892 1089">"Richmond Annex" has been painted on the facings of the bridge. This should be maintained</p>

Overpass:	Lighting:	Pedestrian Railings:	Sidewalk Condition:	Walls/Abutments:	Plantings:	Bridge Facings:
 <p style="text-align: center;">Central Avenue</p>	<p>24/7 Illumination should be installed above sidewalks</p>	<p>Pedestrian railing have been installed</p>	<p>Fill any available area with decorative pavers</p>	<p>The overpass rests on dirt embankments that should be covered with decorative pavers</p>	<p>Upgrade current planted areas</p>	<p>Street name or district should be painted on the bridge facings</p>
 <p style="text-align: center;">2nd Street @ I-580</p>	<p>24/7 Illumination should be installed above sidewalks</p>	<p>Install pedestrian railings on both sides of the street</p>	<p>Fill any available area with decorative pavers</p>	<p>The overpass rests on dirt embankments that should be covered with decorative pavers</p>	<p>Areas should be planted with Redwoods</p>	<p>Street name or district should be painted on the bridge facings</p>
 <p style="text-align: center;">I-580 @ Canal</p>	<p>24/7 Illumination should be installed above sidewalks</p>	<p>Install pedestrian railings on both sides of the street</p>	<p>Fill any available area with decorative pavers</p>	<p>Install <u>ceramic tile</u> murals on each concrete abutment</p>	<p>Upgrade current planted areas</p>	<p>Encourage continued growth of vines that are beginning to cover facings</p>

This page intentionally left blank